

Req/Changes Project ID: 124 Project Description: St. Bonaventure Church Multipurpose Bldg & HOPE Exp  
 JOB ID: 1032 Job Description: St. Bonaventure Church - Multipurpose Bldg. & HOPE Expansion

96 CLO (Closed) 5 OUT (Outstanding) 2 VOID (VOID)

- Change In Condition
- Proceed with Work
- Request for Information
- Request for Proposal
- NonConformance / Corrective Action / Prev. Action

ID:	id	Rev	Job	status:	RE:	Date Issued:	to recipient:	to company:	Req'd Date:	Initiated By	Ref. #	Desc.	method:	File Location:	from co:	signed_by:	# of pages	F ▲	
105	1854		1032			10/21/2008	Luis Barrios, Jr	DDWA							SNYDER				
	104	1853	1032			10/21/2008	Luis Barrios, Jr	DDWA							SNYDER				
	103	1624	1032	OUT	Mailbox @ gate	4/3/2006	Luis Barrios, Jr	DDWA	4/5/2006	SNYDER LANC		Please provide Sny			SNYDER	Mel Lopez	1		
	102	1599	1032	OUT	Revised Footing for Gate & Fence	3/30/2006	Luis Barrios, Jr	DDWA	3/31/2006	SNYDER LANC		Per the walk thru @			SNYDER	Mel Lopez	1		
	101	1481	1032	OUT	Chain link fence gate post anchors	3/15/2006	Luis Barrios, Jr	DDWA	3/15/2006	SNYDER LANC		Please confirm that			SNYDER	Marivic S. Ha	1		
	100	1446	1032	CLO	Stainless Steel around Roll-up door	3/3/2006	Luis Barrios, Jr	DDWA	3/5/2006	SNYDER LANC		Per DC #40, please			SNYDER	Marivic S. Ha	1		
	99	1436	1032	OUT	Planter along Northwest wall by Lobby 108	3/1/2006	Daniel D. White	DDWA	3/2/2006	ST. BONAVENTURE		Sheet A1.2 indicate			SNYDER	Marivic S. Ha	1		
	98	1426	1032	CLO	Revisions to Door 13, 15, 19 & 20	2/23/2006	Luis Barrios, Jr	DDWA	2/24/2006	ST. BONAVENTURE		Per Linda's request			SNYDER	Marivic S. Ha	1		
	97	1422	1032	CLO	Ceiling Fan & Projection Screen	2/23/2006	Luis Barrios, Jr	DDWA	2/23/2006	SNYDER LANC		Please provide loca			SNYDER	Marivic S. Ha			
	96	1421	1032	CLO	Signage Requirements	2/23/2006	Luis Barrios, Jr	DDWA	2/24/2005	SNYDER LANC		SL's scope for sign			SNYDER	Marivic S. Ha	1		
	95	1411	1032	CLO	Ceramic Tile & Carpet Transition at Reception	2/17/2006	Luis Barrios, Jr	DDWA	2/20/2006	SNYDER LANC		Please provide layo			SNYDER	Marivic S. Ha	1		
	94	1410	1032	OUT	Keying for cabinet and drawer locks	2/17/2006	Luis Barrios, Jr	DDWA	2/20/2006	TAHITI CABINET		Please provide key			SNYDER	Marivic S. Ha	1		
	93	1408	1032	CLO	Light Fixture in Room 113	2/15/2006	Luis Barrios, Jr	DDWA	2/16/2006	SNYDER LANC		Room 113 is not w			SNYDER	Marivic S. Ha	1		
	92	1388	1032	CLO	Lights in Room 108 & 109	2/15/2006	Daniel D. White	DDWA	2/16/2006	DDWA		Per our previous ci			SNYDER	Marivic S. Ha	1		
	91	1387	1032	CLO	2" CW Connection	2/7/2006	Daniel D. White	DDWA	2/9/2006	SNYDER LANC		Per our meeting on			SNYDER	Marivic S. Ha	1		
	90	1385	1032	CLO	Lighting Override Switch Location @ MP Bldg	2/3/2006	Luis Barrios, Jr	DDWA	2/6/2006	SNYDER LANC		Please provide loca			SNYDER	Melissa Lade	1		
	89	1384	1032	CLO	Timer/Shut-Off Switch for Exterior Lights @ H	2/3/2006	Luis Barrios, Jr	DDWA	2/6/2006	SNYDER LANC		There is no timer/sl			SNYDER	Melissa Lade			
	88	1339	1032	CLO	Flooring Finish Requirements in HOPE Room 10	1/23/2006	Luis Barrios, Jr	DDWA	1/24/2006	SNYDER LANC		Per A2.1, the floori			SNYDER	Melissa Lade			
	87	1332	1032	CLO	Electrical Trim Color/Style Confirmation @ HOP	1/19/2006	Luis Barrios, Jr	DDWA	1/20/2006	SNYDER LANC		Please confirm that			SNYDER	Melissa Lade			
	86	1316	1032	CLO	Irrigation Control Panel Location Elevation	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANC		Please Provide Loc			SNYDER	Melissa Lade			
	85	1315	1032	CLO	Elevation for Retaining Wall @ northeast corne	1/18/2006	Luis Barrios, Jr	DDWA	1/25/2006	SNYDER LANC		Please provide Elev			SNYDER	Marivic S. Ha	1		
	84	1314	1032	CLO	Retaining Wall Elevation @ northwest corner c	1/17/2006	Luis Barrios, Jr	DDWA	1/25/2006	SNYDER LANC		Please provide Elev			SNYDER	Melissa Lade	1		
	83	1313	1032	CLO	Gate/Fence @ SE corner between MP Bldg & I	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANC		Insufficient informa			SNYDER	Melissa Lade	1		
	82	1312	1032	CLO	Gate/Fence @ NW corner between MP Bldg &	1/16/2006	Luis Barrios, Jr	DDWA	1/23/2006	SNYDER LANC		Please provide nec			SNYDER	Melissa Lade	1		
	81	1311	1032	CLO	Exterior Paint Colors for HOPE & Multipurpose	1/13/2006	Luis Barrios, Jr	DDWA	1/13/2006	SNYDER LANC		Please provide pair			SNYDER	Melissa Lade	1		
	80	1202	1032	CLO	Ceramic Tile behind Mirrors in Bathrooms 103,	12/28/2005	Luis Barrios, Jr	DDWA	12/29/2005	COASTAL TILE		Sheet A5.2 does n			SNYDER	Melissa Lade			
	79	1199	1032	CLO	Telephone/Computer Data Outlet Locations in I	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	SNYDER LANC		Sheet E2.4 specifi			SNYDER	Melissa Lade			
	78	1198	1032	CLO	Electrical Outlet Required in HOPE Expansion E	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	SNYDER LANC		Per City of Huntingt			SNYDER	Melissa Lade			
	77	1197	1032	CLO	Band Detail at Line D to Cover Bolts	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	AMORT CONS		Please provide deta			SNYDER	Melissa Lade			
	76	1196	A	1032	CLO	Soffit Framing Detail at Accordion Partition	12/27/2005	Luis Barrios, Jr	DDWA	12/28/2005	AMORT CONS		Please provide deta			SNYDER	Melissa Lade		
	75	1195	A	1032	CLO	Carpeting - Confirmation of DDWA Bulletin #11	12/22/2005	Luis Barrios, Jr	DDWA	12/22/2005	SNYDER LANC		This is a confirming			SNYDER	Melissa Lade		
	74	1194		1032	CLO	Millwork Size Verification for File Cabinet & Kit	12/22/2005	Luis Barrios, Jr	DDWA	12/23/2005	TAHITI CABINET		Please verify the fi			SNYDER	Melissa Lade		
	73	1189		1032	CLO	Restroom 103 & 104 - revised wall tile design	12/20/2005	Luis Barrios, Jr	DDWA	12/20/2005	COASTAL TILE		Per DDWA DC 42 (			SNYDER	Marivic S. Ha	1	
	72	1188	A	1032	CLO	HOPE Restroom #105	12/20/2005	Luis Barrios, Jr	DDWA	12/20/2005	SNYDER LANC		Per the DDWA DC ;			SNYDER	Marivic S. Ha	2	
	71	1170		1032	CLO	Layout for Light Fixture types K & L in Multipur	12/12/2005	Luis Barrios, Jr	DDWA	12/13/2005	SNYDER LANC		Please provide a la			SNYDER	Will Scott		
	70	1168		1032	CLO	Hose Bibb HB-1	12/12/2005	Marivic S. Ha	SNYDER LANGS	12/12/2005	ACADEMY ME		Please clarify type			SNYDER	Marivic S. Ha	2	
	69	1162		1032	CLO	Plaster Expansion Joint @ Multipurpose Bldg. -	12/12/2005	Luis Barrios, Jr	DDWA	12/13/2005	SNYDER LANC		6/A2.3 calls for Pla			SNYDER	Will Scott		
	68	1161	B	1032	CLO	Relocation of EF-4	12/9/2005	Luis Barrios, Jr	DDWA	12/12/2005	SNYDER LANC		Mechanical drawin			SNYDER	Marivic S. Ha		
	67	1160	B	1032	CLO	Duct work for AC-1	12/9/2005	Luis Barrios, Jr	DDWA	12/12/2005	SNYDER LANC		The area (west of			SNYDER	Marivic S. Ha	2	
	66	1159	A	1032	CLO	Exit Signage Requirements for Doors 6 & 7 @	12/9/2005	Luis Barrios, Jr	DDWA	12/12/2005	SNYDER LANC		Exit Signage for Door			SNYDER	Will Scott		